




## **NON-REGRESSING STATEMENT**

- Diamond version 1.93.409.1 based on version 1.37.409.3 for HTC\_NOR.
- All the upgraded items (CE, Applications and Radio), and the closed issues are listed clearly in the release notes.
- There is no change without listing between V 1.93.409.1 and V 1.37.409.3, so please go through following pages to see the differences.
- The mainly change of this version :  
  
CE, AP and Radio.
- We highly suggest that you focus on what listed in the release notes to do the necessary tests, and the solved issues will never happen again in the future.

|   |                        |                |
|---|------------------------|----------------|
|  | <b>HTC Corporation</b> | <b>Diamond</b> |
|   | Software Release Note  |                |

| Information             |  |
|-------------------------|--|
| Customer                | HTC_NOR                                |
| ROM Version             | 1.93.409.1                             |
| IPL/IPL_G4/SPL          | spl_1.93_Security.nb                   |
| GSM Radio Stack         | 52.29.25.12H_1.00.25.05                |
| OS Build                | WindowsMobile_6.1_AKU_1.2.3_Build19965 |
| RUU Version             | 3_27_4_1600                            |
| Boot Language           | 0414_NOR                               |
| Model ID / MB Rev.      | DIAM10000                              |
| CID                     | HTC_H10                                |
| Date                    | 2008/7/11 下午 08:26:01                  |
| Purpose of this release | RC                                     |

| Known Issues |             |
|--------------|-------------|
| No.          | Description |
|              |             |

| Application |                       |                          |      |
|-------------|-----------------------|--------------------------|------|
| No.         | Name                  | Version                  | Note |
| 1           | ADOBEPDF              | 2_5_103000_60r2          |      |
| 2           | ALBUM                 | 2_0_18163421_0           |      |
| 3           | ARCSOFT_MMS           | 5_0_27_25                |      |
| 4           | AUDIOBOOSTER          | 2_0_18143227_4           |      |
| 5           | AUDIOMANAGER_ENG      | 1_5_18161432_0           |      |
| 6           | BTBPP                 | 1_6_5_0                  |      |
| 7           | BTFTP                 | 1_2_33281_91             |      |
| 8           | BTSAP                 | 3_1_0_0r2                |      |
| 9           | CAMERA                | 6_00_31516_00            |      |
| 10          | CONCURRENCEMGR        | 1_1_18143521_0000        |      |
| 11          | CONNECTIONSETUP       | 1_5_34564_2              |      |
| 12          | CYBERONVOICESPEEDDIAL | 1_2_b080227_0r3          |      |
| 13          | DSHOW                 | 2_00_080623_0            |      |
| 14          | ENLARGESTARTMENU      | 1_2_34318_100            |      |
| 15          | EZINPUT               | 1_5_31506_1              |      |
| 16          | FMRADIO               | 1_6_18161621_1           |      |
| 17          | FULLSCREENPLAYER      | 1_05_080602_0            |      |
| 18          | GOOGLEMAP             | 2_0_1_33                 |      |
| 19          | HTCGESTURE            | 1_0_30346_1              |      |
| 20          | JBEDJAVA              | 0_0_20080610_2_1         |      |
| 21          | LABYRINTH             | 1_3_5221602_0            |      |
| 22          | LOCKSTREAMDRM         | 1_1_080411_o9_diamond_12 |      |
| 23          | LONGPRESSEDKEY        | 1_1_34078_1              |      |
| 24          | MHUB                  | 6_54_080121_e1           |      |
| 25          | MP3TRIMMER            | 1_1_18143421_2           |      |
| 26          | OPERA_BROWSER_NB      | 9_50_1522_0              |      |
| 27          | OUTLOOKENHANCEMENT    | 1_0_33540_3              |      |
| 28          | PHONECANVAS           | 3_50_31706_1             |      |
| 29          | PICTUREENHANCEMENT    | 1_50_18131521_c2         |      |
| 30          | PLAYSHOW              | 1_0_18162827_0           |      |
| 31          | QUICKGPS              | 1_00_18152630_0          |      |
| 32          | RANDOMACCESS          | 4_0_18133030_0           |      |

|    |                 |                 |  |
|----|-----------------|-----------------|--|
| 33 | RINGTONEPPLUGIN | 1_00_080416_1   |  |
| 34 | RSSHUB          | 2_1_1_1066_r3   |  |
| 35 | SENSORS SDK     | 3_3_18163730_0  |  |
| 36 | SHAREDLL        | 2_0_071002_00v2 |  |
| 37 | SMARTTOUCH      | 1_0_31096_0     |  |
| 38 | STREAMINGMEDIA  | 3_0_18163030_00 |  |
| 39 | TASKMANAGER     | 2_1_34563_100   |  |
| 40 | TOUCHFLO        | 3_0_29946_47    |  |
| 41 | USBTOPCPOPUP    | 1_0_18143432_1  |  |
| 42 | VIDEOTELEPHONY  | 2_0_31227_0     |  |
| 43 | VOICERECORDER   | 1_10_18151728_0 |  |
| 44 | VOLUMECONTROL   | 1_0_18171229_0  |  |
| 45 | XT9_IME         | 1_5_31497_1     |  |
| 46 | YOUTUBE         | 1_0_1816_2629   |  |
| 47 | ZIP             | 1_21_18162332_0 |  |

| Issues Fixed                          |   |  |
|---------------------------------------|---|--|
| No                                    | Description   |  |
| CE<br>1.37.409.3<br>↓<br>1.93.409.1   | 1   | MNO Play name shown improperly on manual network selection list  |
|                                       | 2   | Media player - poor audio quality  |
|                                       | 3   | Due to some customers complain about GPS is very hard to get position fixed even with AGPS enabled recently, and after checking with Radio team we found QCT has changed its algorithm in MSB mode in deciding to create a SUPL session to link to AGPS server for aiding data download. |
|                                       | 4   | Display can not turn on after device enter suspend mode when execute battery life test.  |
|                                       | 5   | Modify the audio CPU lock mechanism and time to improve power consumption.   |
|                                       | 6   | Can't launch MSFT Voice commander sucessfully  |
|                                       | 7   | [SIM LOCK] Implement SIM Unlock mechanism which only allow for 10 failed password entry attempts. Following every failed attempted shall be a display indicating the number of remaining failed attempts.  |
|                                       | 8   | TitleBar may disappear while back to Today   |
|                                       | 9   | The phone canvas will show SIM_BLOCK even the user has released the PUK in HTC's PIN AP.   |
|                                       | 10  | UE Time Zone is not getting synchronized with the live network.  |
|                                       | 11  | Update the number of context setting under the numeric format of operator name.  |
|                                       | 12  | Music bass disappear after unplug/plug wire headset when enable Audio Booster.(Always)   |
|                                       | 13  | WCDMA FDD Band VIII Not included into capabilities when DUT is set by user to R99 mode.  |
|                                       | 14  | Charging current will change from 462 mA to 800 mA after charge device with USB in off mode for 3 minutes.   |
|                                       | 15  | Device will show charging animation on display when "When device is turned on, do not charge the battery when connected to the PC" option is enabled and then suspend device with USB attached.  |
|                                       | 16  | [Opera 9,G-Sensor] G-Sensor is not working after entering suspend mode and than resuming. (Sensor SDK bug)(fail rate: 15/20)   |
| CAMERA 6_00_31364_00 → 6_00_31516_00  |   |  |
| 1                                     | [camera]Screen looks abnormal in action screen after tap power key and camera key at the same time.               |  |
| 2                                     | [Camera]Recive an incoming call while taking a picture, and the Action Screen will display with confused picture. |  |
| 3                                     | (1) Avoid device enter suspend when user has answered a phone call<br>(2) Add sync mechanism with HTC Album       |  |
| ALBUM 2_0_18161424_1 → 2_0_18163421_0 |   |  |
| 1                                     | The Action will display scramble image after take a photo tap view and back button quickly.                       |  |
| 2                                     | The camera preview will black after take a photo then view in Album (3/12)  |  |
| DSHOW 2_00_080526_0 → 2_00_080623_0   |   |  |
| 1                                     | [DRM]The DRM MP4 video file downloaded from PIE or Opera is no sound while playing.                               |  |
| 2                                     | WMP cannot display still image when playing back the 3GP file and MP4 file on the test device.                    |  |
| 3                                     | DUT hung at black screen during usability stress test, and LED keep blinking after unplug AC.(3/38).              |  |
| EZINPUT 1_5_31365_0 → 1_5_31506_1     |   |  |
| 1                                     | [IME_EZ_Compact QWERTY]No able to input ä and ö and doesn't display on WCL.                                       |  |
| 2                                     | [IME_EZ_Compact QWERTY]Can't input ø,æ,Ø,Æ letters with Compact QWERTY.   |  |
| 3                                     | [Ez sip]Receive a call(VT/vocie) when Launch sip menu,incoming call can't pop up.                                 |  |
| 4                                     | [IME_EZ_Compact QWERTY]Fast type words in abc mode then tap .com immediately will malfunction in input URL box.   |  |

AP

|  |  |
|--|--|
| 5  | [IME_EZ_Full QWERTY]In XT9 mode, the symbol won't display on the candidate list and will input directly.   |
| 6  | [Arcsoft MMS]It'll take around 15 seconds from select a MMS sample file to enter the composer.   |
| 7  | [IME_EZ_Compact QWERTY]The smart search function will detect to wrong contact after specific steps.  |
| 8  | [EZ SIP]In gmail tap "password" can be input "Passwords" but not display the characters and directly into "".  |
| <b>OPERA_BROWSER_WWE 9_50_1522_0</b>                                     |  |
| 1  | Bug 343399 has been fixed. In delete dialog the proper question is now displayed.  |
| 2  | Merged bug 336927, added setting in opera.ini to disable resume of downloads   |
| 3  | Fix for change request #334008: Do not open home page more than once.  |
| 4  | Fix for Bug 343699: Opera fail to open file when download the file when the opera.ini setting is missing.  |
| 5  | Fix for Bug 343664:Opera should force to use CMWAP connection to connect on internet.  |
| 6  | bug 324454, Default favorite icon is too big   |
| 7  | Bug 333682 added define #NO_VTEL to disable handling of tel-av links.  |
| 8  | Fix for bug #342530: Forcing the resulting url into "utf-8" encoding.  |
| <b>PHONECANVAS 3_50_31308_4 → 3_50_31706_1</b>                           |  |
| 1  | [Phone Experience Enhance]There is a "?" symbol on edit box of text message in phone setting.  |
| 2  | Speaker can't be activated if headphones are plugged during VT calls.  |
| 3  | VT Shortcut missing in contacts  |
| 4  | Mute function did not work after flipping device while got MT call and enable password lock.(Always)   |
| 5  | [Phone Experience Enhance]"Save to contacts" can not be displayed after finishing a MO/MT call.  |
| 6  | [Phone Canvas]In Call history, select a specific item of call log and press action key. It will show sliding tabs of Manila before the specific phone number's call log. |
| 7  | [USSD][GFT]DUT incoming call phone canvas covered by incoming call message bubble if it activates and stay on USSD menu then receives MT voice or VT call.               |
| <b>SENSORS DK 3_3_18153516_0 → 3_3_18163730_0</b>                        |  |
| 1  | [Album]Launch Album via Camera and view a picture, the picture will be displayed with incorrect direction.   |
| 2  | [Camera]Capturing a picture via landscape mode, but it will be saved as incorrect direction.   |
| 3  | modified the angle range of faceup status from 45 to 30 for algorithm 7.   |
| 4  | modified tiling angle threshold from 20 to 30 and rotate angle threshold from 45 to 40 for algorithm7.   |
| <b>STREAMINGMEDIA 3_0_18153213_00 → 3_0_18163030_00</b>                  |  |
| 1  | Live Stream using sdp file extension: Streaming the file Video is displayed after a delay of 5 secs once streaming starts.   |
| <b>TASKMANAGER 2_1_34318_100 → 2_1_34563_100</b>                         |  |
| 1  | The tabs name in the help file and in application are not the same.  |
| 2  | [AP1:Task Manager]When launching phone dialer, tap top right corner of screen ASAP, Quick List and "x" button overlap.   |
| <b>VOLUMECONTROL 1_0_18162230_0 → 1_0_18171229_0</b>                     |  |
| 1  | When the ringtone volume is set by using the stylus, the set volume is not maintained.   |
| <b>XT9_IME 1_5_31456_0 → 1_5_31497_1</b>                                 |  |
| 1  | Usability: The XT9 option keeps re-enabling when switching to another text box on the same edit page.  |
| <b>ZIP 1_21_18141127_1 → 1_21_18162332_0</b>                             |  |
| 1  | The icon of ZIP is inconsistent between programs and task manager.   |
| Radio<br>52.26a.25.09H<br>_1.00.25.03<br>↓<br>52.29.25.12H<br>1.00.25.05 | 1 SR 1080761: [7201A][CHT] Failed to read MIB during manual PLMN search  |
|  | 2 RRC seem to be stuck at RRCCU_WAIT_FOR_CELL_UPDATE_CONFIRM.  |
|  | 3 AT command +CSCA doesn't work and MO SMS cannot be sent.   |
|  | 4 Implement preferred domain, RAT, and mode selection when +COPS=0/1/4 is executed.  |
|  | 5 The response for +COPS=0 is sent immediately instead of being sent after unsolicited +CREG is sent.  |
|  | 6 WinCE cannot handle USSD general, invoke, and error code tag problems in RELEASE COMPLETE msg.   |
|  | 7 Enhance phonebook number match utility   |
|  | 8 When sim puk lock the attach command will be hung until at command time out  |
|  | 9 DUT shows no SIM for one specify TCC 3G SIM  |
|  | 10 Ignore unused GPIOs configuration for MSM7206A  |
|  | 11 Added AT+L1OPT for L1 options   |
|  | 12 Reset RTR6285 on next sleep when L1 detect abnormal RTR6285   |
|  | 13 Clear non-DRX timer flag when setup early camping   |
|  | 14 Some specific WCDMA TX RF NV items are not loaded   |
|  | 15 Add AT+CPPP to support change of PPP auth between PAP (+CPPP=2) and CHAP(+CPPP=3)   |

| Remark |             |
|--------|-------------|
| No     | Description |
|        |             |